

# Fraction Conversion Chart



$\frac{1}{64}$	<b>.015625</b>
$\frac{1}{32}$	<b>.03125</b>
$\frac{3}{64}$	<b>.046875</b>
$\frac{1}{16}$	<b>.0625</b>
$\frac{5}{64}$	<b>.078125</b>
$\frac{3}{32}$	<b>.09375</b>
$\frac{7}{64}$	<b>.109375</b>
$\frac{1}{8}$	<b>.125</b>
$\frac{9}{64}$	<b>.140625</b>
$\frac{5}{32}$	<b>.15625</b>
$\frac{11}{64}$	<b>.171875</b>
$\frac{3}{16}$	<b>.1875</b>
$\frac{13}{64}$	<b>.203125</b>
$\frac{7}{32}$	<b>.21875</b>
$\frac{15}{64}$	<b>.234375</b>
$\frac{1}{4}$	<b>.25</b>
$\frac{17}{64}$	<b>.265625</b>
$\frac{9}{32}$	<b>.28125</b>
$\frac{19}{64}$	<b>.296875</b>
$\frac{5}{16}$	<b>.3125</b>
$\frac{21}{64}$	<b>.328125</b>
$\frac{11}{32}$	<b>.34375</b>
$\frac{23}{64}$	<b>.359375</b>
$\frac{3}{8}$	<b>.375</b>
$\frac{25}{64}$	<b>.390625</b>
$\frac{13}{32}$	<b>.40625</b>
$\frac{27}{64}$	<b>.421875</b>
$\frac{7}{16}$	<b>.4375</b>
$\frac{29}{64}$	<b>.453125</b>
$\frac{15}{32}$	<b>.46875</b>
$\frac{31}{64}$	<b>.484375</b>
$\frac{1}{2}$	<b>.5</b>

$\frac{33}{64}$	<b>.515625</b>
$\frac{17}{32}$	<b>.53125</b>
$\frac{35}{64}$	<b>.546875</b>
$\frac{9}{16}$	<b>.5625</b>
$\frac{37}{64}$	<b>.578125</b>
$\frac{19}{32}$	<b>.59375</b>
$\frac{39}{64}$	<b>.609375</b>
$\frac{5}{8}$	<b>.625</b>
$\frac{41}{64}$	<b>.640625</b>
$\frac{21}{32}$	<b>.65625</b>
$\frac{43}{64}$	<b>.671875</b>
$\frac{11}{16}$	<b>.6875</b>
$\frac{45}{64}$	<b>.703125</b>
$\frac{23}{32}$	<b>.71875</b>
$\frac{47}{64}$	<b>.734375</b>
$\frac{3}{4}$	<b>.75</b>
$\frac{49}{64}$	<b>.765625</b>
$\frac{25}{32}$	<b>.78125</b>
$\frac{51}{64}$	<b>.796875</b>
$\frac{13}{16}$	<b>.8125</b>
$\frac{53}{64}$	<b>.828125</b>
$\frac{27}{32}$	<b>.84375</b>
$\frac{55}{64}$	<b>.859375</b>
$\frac{7}{8}$	<b>.875</b>
$\frac{57}{64}$	<b>.890625</b>
$\frac{29}{32}$	<b>.90625</b>
$\frac{59}{64}$	<b>.921875</b>
$\frac{15}{16}$	<b>.9375</b>
$\frac{61}{64}$	<b>.953125</b>
$\frac{31}{32}$	<b>.96875</b>
$\frac{63}{64}$	<b>.984375</b>
1	<b>1</b>